







1		1A	x28
2		Ø8x36	x26
3		3A	x24
4			x6
5		Ø5x17	x2
6		Ø3x20	x2
7		Ø4x35	x10
8			x2
9		Ø3x30	x1
10			

MIT7

KOLEJNOŚĆ MONTAŻU
MONTAZNÍ SEQUENCIE
THE FITTINGS SEQUENCE OF THE
GAMS AND DOWELS.
DIE MONTAGEFOLGE VON
EXZERNEN UND DÜBELN.



A

